

PHONE #

EQUIPMENT 1954

Harry Ferguson TO-30 1954-19

TO-127304

Continental

Z129-36677

WORK THAT NEEDS DONE w/ Shop

00751.9 Hours

DESCRIPTION
Crankshaft Broken in two
15351 Replaced Parts on Harry Ferguson Tractor
hp Drawbar 19
PTO 28
Belt 29

1 C830631M) Gasket Set

MATERIAL USED

QTY	PART #	DESCRIPTION
1		Crankshaft
1	180241M91	clutch, Pressure Plate & Bearings
1		Crankshaft turn Fr
1	176134-1	Gasket Set head (top)
1	RP281295	Main Bearing Set
1	RP2812684	Red Main Bearing Set
1		Flywheel Resurface
1	M-24	Battery
OIL USED		
1	5 quarts	TSX
1	51010	oil filter

Equipment Pick up Policy

Connecting Rod

We make every effort to repair your equipment as quickly as possible. When the work is

QTY	PART #	DESCRIPTION	PRICE
2	TSX	Quarts	
1	ARC3233	Carb Kit	
1		Ign Switch	
1	9626944	O-Ring	
	RP281295	Main Bearing Set	
	17650169M	Crankshaft	

OIL USED

Freight

Equipment Pick up Policy

We make every effort to repair your equip
Customer equipment is not left outside, sp.

**Repaired Equipment which is not picked u
90 days after notification** will be considere

** Notification includes message via ar

X

Starter Rebuild