



		2815 West Hwy 50 - Emporia, KS 66801 (620) 343-6723 - Fax: (620) 343-6793	
COFFEY COUNTY SHERIFFS OFFICE 605 NEOSHO ST. PO BOX 226 BURLINGTON, KS 66839		2020 Year	
DODGE Make		DURANGO Model	
620-490-1685 Body		PURSUIT AWD	
620-364-2123 Home Phone		BLACK Color	
620-364-2123 Work Phone		00/00/00 Delivery Date	
1C4SDJFT0LC369707 Vehicle Identification Number		03/01/21 License Number	
MIKE ROSS Service Advisor / Tag #		In-Service Date	
110971 Mileage In		09/26/23 R/O Open Date	
10/16/23 Reprint		09/26/23 R/O Close Date	
110972 Mileage Out		6074541/1 Status	
SERVICE DEPARTMENT HOURS 7:30 a.m. to 5:30 p.m. Monday - Friday 8:00 a.m. to 1:00 p.m. Saturday		R/O Number	

DESCRIPTION OF SERVICE AND PARTS	AMOUNT
----------------------------------	--------

AR#:

#1 - MR T1: GENERAL REPAIR

service 4wd warning and traction control warning also on, ck & advise *242*

Caused by
test & replace abs module, transfer case shift
motor, and drive train control module, clear
codes, verify operation

Tech: Alejandro Mendoza(242)	Installed	68442478AB :MODULE: ANTI-LOCK BRAKE SYST	1@196.00
	Installed	OR600938 :TRANSFER CASE MOTOR	1@513.11
	Installed	68423302AA :MODULE: TRANSFER CASE CONTR	1@303.40
Sub Total:		Labor: 464.00 Parts: 1012.51	Total: 1476.51

#2 - MR SK: 5K MILE RECOMMENDED MAINTENANCE, INCLUDES CHANGE

Tech: Alejandro Mendoza(242)	Installed 27060MP :OIL FILTER	1@4.28
Installed 5W20 :UNIV XHD SN GF-5	Installed ATF :SYN ECO ULTRA MV	7@3.84
Sub Total: Labor: 21.47	Parts: 44.16	Total: 65.63
2@6.50		

#3 - MR RT: ROTATE TIRES & SET TIRE PSI

Tech: Alejandro Mendoza(242)
Sub Total: Labor: 19.95 Parts: .00 Total: 19.95

#4 - MR CSF: COOLING SYSTEM FLUSH, INCLUDES FLUSH COOLING SYSTEM

LABOR	
PARTS	
DEDUCTIBLE	
SUBLET	
SHOP SUPPLIES	
HAZARDOUS MATERIALS	
SALES TAX OR TAX I.D.	
SPECIAL ORDER DEPOSIT	
DISCOUNTS	
TOTAL DUE	

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

DISCLAIMER OF WARRANTIES. Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply which is prohibited by law.

NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS.

X



Celly's Auto Repair
213 N Ogden, PO Box 427
Lebo, KS. 66856
Phone: 620-256-6411 Fax: 620-256-6036

INVOICE

Printed Date: 09/17/2024

Work Completed: 09/17/2024

COFFEY CO SHERIFF

2020 Dodge - Durango Pursuit - 5.7L, V8 (345CI) VIN(T)

Odometer In : 152513

Lic # : B0312

Unit # : 09

VIN # : 1C4SDJFT0 LC369707

Part Description	Qty	Ext	Labor Description	Ext
------------------	-----	-----	-------------------	-----

Exhaust Manifold	1.00	174.28	EXHAUST MANIFOLD - Remove & Replace - V8,5.7L	472.50
------------------	------	--------	---	--------

674-257			Eng Right Side	
---------	--	--	----------------	--

5W20 - ENGINE OIL Size: QUART	7.00	3.81	Lube, oil, and filter 5W20	31.50
-------------------------------	------	------	----------------------------	-------

5W20				
------	--	--	--	--

OIL FILTER	1.00	4.01	Lubricate and check chassis. Change oil and oil filter. Check air	
------------	------	------	---	--

27060MP			filter and breather filter. Check all fluid levels and tire pressures.	
---------	--	--	--	--

Shop Supplies			Perform basic safety inspection. Road test vehicle.	
---------------	--	--	---	--

Fluid Capacity:	1.91		Engine Oil - Volume: 7.00 QTS. (6.62L) - API - SAE 5W-20; 5.7L Eng	
-----------------	------	--	--	--

- w/filter				
------------	--	--	--	--

TIRE ROTATION				n/c
---------------	--	--	--	-----

ROTATE TIRES AND TORQUE LUG NUT TO FACTORY SPECS.				
---	--	--	--	--

Hazardous Materials				3.98
---------------------	--	--	--	------

Ext				
-----	--	--	--	--

--	--	--	--	--

--	--	--	--	--

--	--	--	--	--

--	--	--	--	--

--	--	--	--	--

--	--	--	--	--

--	--	--	--	--

--	--	--	--	--

--	--	--	--	--

--	--	--	--	--

--	--	--	--	--

--	--	--	--	--

--	--	--	--	--

--	--	--	--	--

--	--	--	--	--

--	--	--	--	--

--	--	--	--	--

--	--	--	--	--

--	--	--	--	--

--	--	--	--	--

--	--	--	--	--

--	--	--	--	--

--	--	--	--	--

--	--	--	--	--

--	--	--	--	--

--	--	--	--	--

--	--	--	--	--

--	--	--	--	--

--	--	--	--	--

--	--	--	--	--

--	--	--	--	--

--	--	--	--	--

--	--	--	--	--

--	--	--	--	--

--	--	--	--	--

--	--	--	--	--

--	--	--	--	--

--	--	--	--	--

--	--	--	--	--

--	--	--	--	--

--	--	--	--	--

--	--	--	--	--

--	--	--	--	--

--	--	--	--	--

--	--	--	--	--

--	--	--	--	--

Org. Est. # 007585

7167

INVOICE

Celly's Auto Repair
213 N Ogden, PO Box 427
Lebo, KS. 66856
Phone: 620-256-6411 Fax: 620-256-6036



INVOICE

Printed Date: 11/20/2024 Work Completed: 11/20/2024

COFFEY CO SHERIFF 605 NEOSHO ST Burlington, KS 66839 Office 620-364-2123

2020 Dodge - Durango Pursuit - 5.7L V8 (345CI) VIN(T) Lic #: B0312 Unit #: 09 VIN #: 1C4SDJFT0 LC369707

Part Description / Number Qty Sale Ext Labor Description Ext

ANTIFREEZE Size: GALLON	3.00	11.55	34.65	RADIATOR HOSE - Remove & Replace - V8, Normally Aspirated Lower	94.50
HOSE, Radiator Outlet	1.00	119.74	119.74	Fluid Capacity:	
68269478AA				Engine Oil - Volume: 7.00 QTS. (6.62L) - API - SAE 5W-20; 5.7L Eng	
Cabin Air Filter - NAPA Gold	1.00	32.60	32.60	Lube, oil, and filter 5W20	31.50
4017				Lubricate and check chassis. Change oil and oil filter. Check air	
OIL FILTER	1.00	4.01	4.01	filter and breather filter. Check all fluid levels and tire pressures.	
27060MP				Perform basic safety inspection. Road test vehicle.	
5W20 - ENGINE OIL Size: QUART	7.00	3.81	26.67	TIRE ROTATION	n/c
5W20				ROTATE TIRES AND TORQUE LUG NUT TO FACTORY SPECS.	
Shop Supplies			2.02	Hazardous Materials	1.00

Org. Estimate 346.69 Revisions 0.00 Current Estimate 346.69 Labor: 126.00 Parts: 219.69 HazMat: 1.00 SubTotal: 346.69 Tax: 0.00 Total: 346.69 Bal Due: \$346.69

[Payments -] 001 - 60 - 5392 Lauren Hull

Vehicle Received: 11/20/2024 Customer Number: 120

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one years or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Disclaimer: Wheels need to be rechecked within 100 Miles. If wheels are not rechecked and torqued to specs Celly's Auto Repair is not responsible for wheels coming loose.

Late Fee: Any Invoice over 30 days past due is subject to a 10% late fee.

Signature _____ Date _____

Email Address: cellysautorepair@gmail.com

INVOICE
7338
Org. Est. # 007800

Celly's Auto Repair
213 N Ogden, PO Box 427
Lebo, KS. 66856
Phone: 620-256-6411 Fax: 620-256-6036

INVOICE
COFFEY CO SHERIFF
605 NEOSHO ST
Burlington, KS 66839
Office 620-364-2123

2020 Dodge - Durango Pursuit - 5.7L V8 (345CI) VIN(T)
Lic #: B0312
Unit #: 09
VIN #: 1C4SDJFT0 LC369707

Part Description / Number Qty Sale Ext Labor Description Ext

Brake Pads - Front - Fleet	FT8856A	1.00	126.09	126.09	BRAKE SHOES &/OR PADS - Remove & Replace -	105.00
Brake Rotor - Front - Fleet	FT880870	2.00	145.73	291.46	Front Axle - [Includes: Clean, lube and/or replace Brake Hardware as necessary. Adjust Brakes (where applicable). Includes: Repack Wheel Bearings (where applicable). DOES NOT include refinishing.]	105.00
Brake Rotor - Rear - Fleet	FT880869	2.00	173.14	346.28	Rear Axle - [Includes: Clean, lube and/or replace Brake Hardware as necessary. Adjust Brakes (where applicable). Includes: Repack Wheel Bearings (where applicable). DOES NOT include refinishing.]	105.00
Brake Pads - Rear - Ultra-Premium -	UP8698X	1.00	83.00	83.00	Hazardous Materials	1.66
Shop Supplies						

Org. Estimate 1,066.37 Revisions 0.00 Current Estimate 1,066.37 Labor: 210.00 Parts: 854.71 HazMat: 1.66 SubTotal: 1,066.37 Tax: 0.00 Total: 1,066.37 Bal Due: \$1,066.37

Vehicle Received: 12/19/2024 Customer Number: 120
001-60-5392

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one years or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.
Disclaimer: Wheels need to be rechecked within 100 Miles, if wheels are not rechecked and torqued to specs Celly's Auto Repair is not responsible for wheels coming loose.
Late Fee: Any invoice over 30 days past due is subject to a 10% late fee.
Signature
Date



CELLY'S Auto Repair
213 N Ogden, PO Box 427
Lebo, KS. 66856
Phone: (620)-256-6411 | Fax: (620)-256-6036

Invoice # 007750

Original Est # 8229

Invoice

COFFEY CO SHERIFF -

2020 Dodge - Durango - Pursuit

Work Complete: 03/17/2025

Balance Due: \$0.00

Paid

605 NEOSH ST
Burlington, KS. 66839
Office: 620-364-2123
VIN: 1C4SDJFT0 LC369707
License Plate: B0312 KS
Color: BLACK
Unit: 09

Type	Description	Part #	Qty/Hr	Sale/Rate	Total
------	-------------	--------	--------	-----------	-------

Lube, Oil, Filter

\$80.04

Note Fluid Capacity:
Engine Oil - Volume: 7.00 QTS. (6.62L) - API - SAE 5W-20; 5.7L Eng - w/Filter

Labor	Lube, oil, and filter 5W20	0.30 hr	\$110.00	\$33.00
-------	----------------------------	---------	----------	---------

Lubricate and check chassis. Change oil and oil filter. Check air filter and breather filter. Check all fluid levels and tire pressures. Perform basic safety inspection. Road test vehicle.

Part	OIL FILTER	27060MP	1.00	\$4.01
------	------------	---------	------	--------

Part	WIPER BLADE	NP21	2.00	\$8.18
------	-------------	------	------	--------

Part	5W20 - ENGINE OIL	5W20	7.00	\$3.81
------	-------------------	------	------	--------

Parts: \$47.04	Labor: \$33.00	Tax: \$0.00	Total: \$80.04
----------------	----------------	-------------	----------------

Order

Misc	Haz Mat.	\$0.26
Misc	Shop Supplies	\$0.73
Total:		\$0.99

Thank you for your business.

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one years or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Disclaimer: Wheels need to be rechecked within 100 Miles, if wheels are not rechecked and torqued to specs Celly's Auto Repair is not responsible for wheels coming loose.

Late Fee: Any invoice over 30 days past due is subject to a 10% late fee.

Payment

Check Paid \$81.03 on 4/4/2025 Transaction: 108380

Technician(s): Moldovan, Marcel

Copyright © Mitchell Repair Information Company LB11241



Celly's Auto Repair
213 N Ogden, PO Box 427
Lebo, KS, 66656

Phone: (620)-256-6411 | Fax: (620)-256-6036

Invoice # 007452
Original Est # 7913

Invoice

COFFEY CO SHERIFF -

2020 Dodge - Durango - Pursuit

Work Complete: 01/14/2025
Service Advisor: Ashley Moldovan
Customer ID: 120
License Plate: B0312 KS
Color: BLACK
Unit: 09
VIN: 1C4SDJFT0 LC369707
5.7L, V8 (345CI) VIN(T)
Odometer: In 167,532

Type	Description	Part #	Qty/Hr	Sale/Rate	Total
------	-------------	--------	--------	-----------	-------

Job Title	\$62.18				
-----------	---------	--	--	--	--

Labor	Lube, oil, and filter 5W20	0.30 hr	\$105.00	\$31.50
-------	----------------------------	---------	----------	---------

Lubricate and check chassis. Change oil and oil filter. Check air filter and breather filter. Check all fluid levels and tire pressures. Perform basic safety inspection. Road test vehicle.

Note	Fluid Capacity: Engine Oil - Volume: 7.00 QTS. (6.62L) - API - SAE 5W-20; 5.7L Eng - w/Filter
------	--

Part	5W20 - ENGINE OIL	7.00	\$3.81	\$26.67
Part	OIL FILTER	1.00	\$4.01	\$4.01

Parts: \$30.68	Labor: \$31.50	Tax: \$0.00	Total: \$62.18
----------------	----------------	-------------	----------------

Misc	Haz Mat.	\$0.25
Misc	Shop Supplies	\$0.73
Total: \$0.98		

Thank you for your business.

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one year or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Disclaimer: Wheels need to be rechecked within 100 Miles, if wheels are not rechecked and torqued to specs Celly's Auto Repair is not responsible for wheels coming loose.

Late Fee: Any invoice over 30 days past due is subject to a 10% late fee.

Labor	\$31.50
Parts	\$30.68
HazMat	\$0.25
Supplies	\$0.73
Subtotal	\$62.18
Labor Tax	\$0.00
Parts Tax	\$0.00
Order Total:	\$63.16

Payment
Check Paid \$63.16 on 2/4/2025 Transaction: 107698

Signature _____
Technician(s): Neary, Jack

Customer and Vehicle Report

Print Date: 09/15/2025

Vehicle: 2020 Dodge - Durango Pursuit, 5.7L,V8 (345CI) VIN(T), B0312, 09

Average Daily Mileage: 132

Totals for Invoice:	Parts	Labor	Discount	Subtotal	Haz Mat	Supplies	Tax	Total
	736.95	696.00	0.00	1,432.95	5.50	6.85	0.00	1,445.30

Invoice: 003619, Posted On: 04/04/2023, SW: Moldovan, Ashley

Odometer in: 91,021 Odometer Out: 0

Time Description	Part No.	Category	Technician	Qty	Sale	Extd	Price	Rate
- Diagnose air conditioning system NO LEAKS FOUND; AC SYSTEM WAS EMPTY OF FREON; WOULD LIKE TO RECHECK AT A LATER DATE		A/C & Heating	Marcel Moldovan		0.00	0.00		95.00
1.50 AC SERVICE - 1234YF Service air conditioner. Check condition of all belts and lines. Evacuate and recharge with reclaimed R-134. Test system performance.			Marcel Moldovan	1.50	142.50	142.50		95.00
- 1234YF FREON				34.08	8.75	298.20		8.75
Totals for Invoice:	298.20	142.50	0.00	440.70	1.13	2.77	0.00	444.60

Totals for Owner:	Parts	Labor	Discount	Subtotal	Haz Mat	Supplies	Tax	Total
	4,104.56	2,438.25	0.00	6,542.81	19.96	43.22	0.00	6,605.99

Print Date: 09/15/2025

Average Daily Mileage: 132

Totals for Invoice:		Parts	Labor	Discount	Subtotal	Haz Mat	Supplies	Tax	Total
		35.23	30.00	0.00	65.23	0.24	0.73	0.00	66.20

er Out: 0

Time	Description	Part No.	Category	Technician	Qty	Sale	Extd	Price	Rate
0.30	Lube, oil, and filter 5W20 Lubricate and check chassis. Change oil and oil filter. Check air filter and breather filter. Check all fluid levels and tire pressures. Perform basic safety inspection. Road test vehicle.		Maintenance	Brock Scharltz	0.30	30.00	30.00		100.00
Notes - Fluid Capacity: Engine Oil - Volume: 7.00 QTS. (6.62L) - API - SAE 5W-20; 5.7L									
	Eng - w/Filter	5W20	Maintenance		7.00	4.46	31.22	4.46	
-	5W20- ENGINE OIL	27060MP			1.00	4.01	4.01	4.01	
-	OIL FILTER								
Totals for Invoice:					Subtotal	Haz Mat	Supplies	Tax	Total
					65.23	0.24	0.73	0.00	66.20

er Out: 0

Time	Description	Part No.	Category	Technician	Qty	Sale	Extd	Price	Rate
5.30	CONDENSER - Remove & Replace - V8,Normally Aspirated - [Includes: R&I Front Bumper Cover. DOES NOT include drain and refill Transmission Fluid or Fluid Level check.] - [DOES NOT include Air Conditioning System recover, evacuate and/or recharge.]			Marcel Moldovan	5.30	503.50	503.50		95.00
	LABOR TO REMOVE BRUSH GUARD AND REPLACE CONDENSER								
-	CONDENSER, Air Conditioning	68232606AB			1.00	438.75	438.75	438.75	
1.50	AC SERVICE - 1234YF			Marcel Moldovan	1.50	142.50	142.50		95.00
	Service air conditioner. Check condition of all belts and lines. Evacuate and recharge with reclaimed R-134. Test system performance.								
-	1234YF FREON	1234YF			34.08	8.75	298.20	8.75	
-	PICK UP PARTS					50.00	50.00		
	PICK UP PARTS								

Customer and Vehicle Report

Print Date: 09/15/2025

Vehicle: 2020 Dodge - Durango Pursuit, 5.7L, V8 (345CI) VIN(T), B0312, 09

Average Daily Mileage: 132

Invoice: 005551, Posted On: 02/22/2024, SW: Moldovan, Marcel

Odometer in: 125,523 Odometer Out: 0

Time	Description	Part No.	Category	Technician	Qty	Sale	Extd	Price	Rate
	Lubricate and check chassis. Change oil and oil filter. Check air filter and breather filter. Check all fluid levels and tire pressures. Perform basic safety inspection. Road test vehicle.								
-	5W20 - ENGINE OIL	5W20			7.00	9.15	64.05	9.15	
-	OIL FILTER	27060MP			1.00	4.01	4.01	4.01	
-	Cabin Air Filter	4017			1.00	32.60	32.60	32.60	
Totals for Invoice:									
			100.66						
						0.00			
							132.16		
								0.25	
								0.94	
									133.35

Invoice: 005253, Posted On: 01/04/2024, SW: Moldovan, Ashley

Odometer in: 120,712 Odometer Out: 0

Time	Description	Part No.	Category	Technician	Qty	Sale	Extd	Price	Rate
0.30	Lube, oil, and filter 5W20 Lubricate and check chassis. Change oil and oil filter. Check air filter and breather filter. Check all fluid levels and tire pressures. Perform basic safety inspection. Road test vehicle.		Maintenance	Brock Schartz	0.30	31.50	31.50		105.00
Notes - Fluid Capacity: Engine Oil - Volume: 7.00 QTS. (6.62L) - API - SAE 5W-20; 5.7L									
	Eng - w/Filter								
-	5W20- ENGINE OIL	5W20	Maintenance		7.00	4.46	31.22	4.46	
-	OIL FILTER	27060MP			1.00	4.01	4.01	4.01	
Totals for Invoice:				Parts	Labor	Discount	Subtotal	Haz Mat	Supplies
				35.23	31.50	0.00	66.73	0.25	0.73
								Tax	Total
								0.00	67.71

Invoice: 005036, Posted On: 11/20/2023, SW: Moldovan, Ashley

Odometer in: 116,239 Odometer Out: 0

Time	Description	Part No.	Category	Technician	Qty	Sale	Extd	Price	Rate
0.30	Lube, oil, and filter 5W20 Lubricate and check chassis. Change oil and oil filter. Check air filter and breather filter. Check all fluid levels and tire pressures. Perform basic safety inspection. Road test vehicle.		Maintenance	Brock Schartz	0.30	30.00	30.00		100.00
Notes - Fluid Capacity: Engine Oil - Volume: 7.00 QTS. (6.62L) - API - SAE 5W-20; 5.7L									
	Eng - w/Filter								
-	5W20- ENGINE OIL	5W20	Maintenance		7.00	4.46	31.22	4.46	
-	OIL FILTER	27060MP			1.00	4.01	4.01	4.01	

Customer and Vehicle Report

Print Date: 09/15/2025

Vehicle: 2020 Dodge - Durango Pursuit, 5.7L, V8 (345Ci) VIN(T), B0312, 09

Average Daily Mileage: 132

Invoice: 005555, Posted On: 04/18/2024, SW: Moldovan, Ashley

Odometer in: 133,513 Odometer Out: 0

Time	Description	Part No.	Category	Technician	Qty	Sale	Extd	Price	Rate
	Lubricate and check chassis. Change oil and oil filter. Check air filter and breather filter. Check all fluid levels and tire pressures. Perform basic safety inspection. Road test vehicle.								
	Notes - Fluid Capacity: Engine Oil - Volume: 7.00 QTS. (6.62L) - API - SAE 5W-20; 5.7L								
	Eng - w/Filter								
-	5W20 - ENGINE OIL	5W20			7.00	3.81	26.67	3.81	
-	OIL FILTER	27060MP			1.00	4.01	4.01	4.01	
-	Air Filter - NAPA Gold	9756			1.00	50.64	50.64	50.64	
-	Cabin Air Filter	4017			1.00	32.60	32.60	32.60	
Totals for Invoice:									
		113.92							
		Labor	157.50						
		Discount	0.00						
		Subtotal	271.42						
		Haz Mat	1.24						
		Supplies	1.06						
		Tax	0.00						
		Total	273.72						

Invoice: 005725, Posted On: 03/25/2024, SW: Moldovan, Ashley

Odometer in: 129,542 Odometer Out: 0

Time	Description	Part No.	Category	Technician	Qty	Sale	Extd	Price	Rate
0.30	Lube, oil, and filter 5W20		Maintenance	Jack Neary	0.30	31.50	31.50	31.50	105.00
	Lubricate and check chassis. Change oil and oil filter. Check air filter and breather filter. Check all fluid levels and tire pressures. Perform basic safety inspection. Road test vehicle.								
	Notes - Fluid Capacity: Engine Oil - Volume: 7.00 QTS. (6.62L) - API - SAE 5W-20; 5.7L								
	Eng - w/Filter								
-	5W20 - ENGINE OIL	5W20			7.00	9.15	64.05	9.15	
-	OIL FILTER	27060MP			1.00	4.01	4.01	4.01	
Totals for Invoice:									
		68.06							
		Labor	31.50						
		Discount	0.00						
		Subtotal	99.56						
		Haz Mat	0.25						
		Supplies	0.73						
		Tax	0.00						
		Total	100.54						

Invoice: 005551, Posted On: 02/22/2024, SW: Moldovan, Marcel

Odometer in: 125,523 Odometer Out: 0

Time	Description	Part No.	Category	Technician	Qty	Sale	Extd	Price	Rate
	Notes - Fluid Capacity: Engine Oil - Volume: 7.00 QTS. (6.62L) - API - SAE 5W-20; 5.7L								
	Eng - w/Filter								
0.30	Lube, oil, and filter 5W20		Maintenance	Marcel Moldovan	0.30	31.50	31.50	31.50	105.00

Customer and Vehicle Report

Print Date: 09/15/2025

Vehicle: 2020 Dodge - Durango Pursuit, 5.7L V8 (345CI) VIN(T), B0312, 09

Invoice: 006157, Posted On: 06/04/2024, SW: Moldovan, Ashley

Average Daily Mileage: 132

Odometer in: 138,480 Odometer Out: 0

Time	Description	Part No.	Category	Technician	Qty	Sale	Extd	Price	Rate
-	TIRE DISMOUNT	TR DISMOUNT		Dustin Foster	4.00	5.00	20.00	5.00	
-	TIRE MOUNT	TR MOUNT			4.00	5.00	20.00	5.00	
-	TIRE BALANCE	bal			4.00	10.00	40.00	10.00	
Totals for Invoice:			Parts	Labor	Discount	Haz Mat	Supplies	Tax	Total
			842.60	0.00	0.00	0.23	7.84	0.00	850.67

Invoice: 006060, Posted On: 05/16/2024, SW: Moldovan, Ashley

Odometer in: 137,283 Odometer Out: 0

Time	Description	Part No.	Category	Technician	Qty	Sale	Extd	Price	Rate
0.30	Lube, oil, and filter 5W20 Lubricate and check chassis. Change oil and oil filter. Check air filter and breather filter. Check all fluid levels and tire pressures. Perform basic safety inspection. Road test vehicle.		Maintenance	Jack Neary	0.30	31.50	31.50		105.00
Notes - Fluid Capacity: Engine Oil - Volume: 7.00 QTS. (6.62L) - API - SAE 5W-20; 5.7L									
	Eng - w/Filter	5W20			7.00	3.81	26.67	3.81	
-	5W20 - ENGINE OIL	27060MP			1.00	4.01	4.01	4.01	
-	OIL FILTER				0.50	52.50	52.50		105.00
0.50	CABIN AIR FILTER - Remove & Replace FILTER WAS INVOICED ON #5555			Marcel Moldovan					
Totals for Invoice:			Parts	Labor	Discount	Haz Mat	Supplies	Tax	Total
			30.68	84.00	0.00	0.66	0.73	0.00	116.07

Invoice: 005555, Posted On: 04/18/2024, SW: Moldovan, Ashley

Odometer in: 133,513 Odometer Out: 0

Time	Description	Part No.	Category	Technician	Qty	Sale	Extd	Price	Rate
1.20	SHOCK ABSORBER - Remove & Replace - Assembly, Both - [DOES NOT include disassemble or alignment (where applicable).] Notes - SUPPLIED SHOCKS			Marcel Moldovan	1.20	126.00	126.00		105.00
0.30	Lube, oil, and filter 5W20		Maintenance	Marcel Moldovan	0.30	31.50	31.50		105.00

Vehicle: 2020 Dodge - Durango Pursuit, 5.7L, V8 (345Ci) VIN(T), B0312, 09

Invoice: 006660, Posted On: 08/19/2024, SW: Moldovan, Ashley

Time	Description	Part No.	Category	Technician	Qty	Sale	Extd	Price	Rate	Total
-	Battery - NAPA Legend 75 Month 12 Volts Group 49 850 CCA Top Post	9849		Jack Neary	1.00	234.19	234.19	234.19		
Notes - NEED AIR FILTER ON NEXT OIL CHANGE										
Totals for Invoice:		264.87	120.75	0.00		385.62	0.95	2.46	0.00	389.03

Invoice: 006339, Posted On: 07/03/2024, SW: Moldovan, Ashley

Time	Description	Part No.	Category	Technician	Qty	Sale	Extd	Price	Rate	Total
0.30	Lube, oil, and filter 5W20 Lubricate and check chassis. Change oil and oil filter. Check air filter and breather filter. Check all fluid levels and tire pressures. Perform basic safety inspection. Road test vehicle.		Maintenance	Brock Schartz	0.30	31.50	31.50			105.00
Notes - Fluid Capacity: Engine Oil - Volume: 7.00 QTS. (6.62L) - API - SAE 5W-20; 5.7L Eng - w/Filter										
-	5W20 - ENGINE OIL	5W20			7.00	3.81	26.67	3.81		
-	OIL FILTER	27060MP			1.00	4.01	4.01	4.01		
Totals for Invoice:		30.68	31.50	0.00		62.18	0.25	0.73	0.00	63.16

Invoice: 006315, Posted On: 06/28/2024, SW: Moldovan, Ashley

Time	Description	Part No.	Category	Technician	Qty	Sale	Extd	Price	Rate	Total
-	HEADLIGHT	9005N			1.00	17.34	17.34	17.34		
Totals for Invoice:		17.34	0.00	0.00		17.34	0.23	0.73	0.00	18.30

Invoice: 006157, Posted On: 06/04/2024, SW: Moldovan, Ashley

Time	Description	Part No.	Category	Technician	Qty	Sale	Extd	Price	Rate	Total
-	265/60VR18 ALENZA AS ULTRA BL	B001198	Wheels & Tires	Jack Neary	4.00	190.65	762.60	190.65		
-	Excise Tax		Wheels & Tires		4.00	0.25	1.00	0.25		
-	Tire Disposal		Wheels & Tires		4.00	5.00	20.00	5.00		

Customer and Vehicle Report

Print Date: 09/15/2025

Vehicle: 2020 Dodge - Durango Pursuit, 5.7L V8 (345CI) VIN(T), B0312, 09

Average Daily Mileage: 132

Totals for Invoice:	Parts	Labor	Discount	Subtotal	Haz Mat	Supplies	Tax	Total
	54.03	31.50	0.00	85.53	0.25	0.73	0.00	86.51

Invoice: 006778, Posted On: 09/17/2024, SW: Moldovan, Marcel

Odometer in: 152,513 Odometer Out: 0

Time	Description	Part No.	Category	Technician	Qty	Sale	Extd	Price	Rate
4.50	EXHAUST MANIFOLD - Remove & Replace - V8,5.7L Eng Right Side			Brock Scharzt	4.50	472.50	472.50		105.00
-	Exhaust Manifold	674-257							
0.30	Lube, oil, and filter 5W20		Maintenance	Brock Scharzt	1.00	174.28	174.28	174.28	105.00
	Lubricate and check chassis. Change oil and oil filter. Check air filter and breather filter. Check all fluid levels and tire pressures. Perform basic safety inspection. Road test vehicle.				0.30	31.50	31.50		
Notes - Fluid Capacity: Engine Oil - Volume: 7.00 QTS. (6.62L) - API - SAE 5W-20; 5.7L Eng - w/Filter									
-	5W20 - ENGINE OIL	5W20			7.00	3.81	26.67	3.81	
-	OIL FILTER	27060MP			1.00	4.01	4.01	4.01	
-	TIRE ROTATION			Brock Scharzt		0.00	0.00		105.00
ROTATE TIRES AND TORQUE LUG NUT TO FACTORY SPECS.									
Totals for Invoice:									
		204.96							
			Labor			504.00			
			Discount			0.00			
			Subtotal				708.96		
			Haz Mat			3.98			
			Supplies				1.91		
			Tax					0.00	
			Total						714.85

Invoice: 006660, Posted On: 08/19/2024, SW: Moldovan, Ashley

Odometer in: 148,163 Odometer Out: 0

Time	Description	Part No.	Category	Technician	Qty	Sale	Extd	Price	Rate
0.30	Lube, oil, and filter 5W20		Maintenance	Jack Neary	0.30	31.50	31.50		105.00
	Lubricate and check chassis. Change oil and oil filter. Check air filter and breather filter. Check all fluid levels and tire pressures. Perform basic safety inspection. Road test vehicle.								
Notes - Fluid Capacity: Engine Oil - Volume: 7.00 QTS. (6.62L) - API - SAE 5W-20; 5.7L Eng - w/Filter									
-	5W20 - ENGINE OIL	5W20			7.00	3.81	26.67	3.81	
-	OIL FILTER	27060MP			1.00	4.01	4.01	4.01	
0.25	TIRE ROTATION			Jack Neary	0.25	26.25	26.25		105.00
ROTATE TIRES AND TORQUE LUG NUT TO FACTORY SPECS.									
0.60	BATTERY - Remove & Replace - Main				0.60	63.00	63.00		105.00
- [Includes: Test.]									

Print Date: 09/15/2025

Average Daily Mileage: 132

Odometer in: 159,989 Odometer Out: 0

Invoice: 006961, Posted On: 10/16/2024, SW: Moldovan, Ashley										Odometer in: 156,326		Odometer Out: 0					
Time Description		Part No.		Category		Technician		Qty		Sale		Extd		Price		Rate	
				Maintenance		Brock Schartz		0.30		31.50		31.50				105.00	

Odometer in: 156.326 Odometer Out: 0

(C) 2020 Mitchell Repair Information Company, LLC custvehsum GM101421

Customer and Vehicle Report

Print Date: 09/15/2025

Vehicle: 2020 Dodge - Durango Pursuit, 5.7L,V8 (345CI) VIN(T), B0312, 09

Invoice: 007338, Posted On: 12/20/2024, SW: Moldovan, Marcel

Average Daily Mileage: 132

Odometer in: 163,874 Odometer Out: 0

Time	Description	Part No.	Category	Technician	Qty	Sale	Extd	Price	Rate
1.00	BRAKE SHOES &/OR PADS - Remove & Replace - Rear Axle - [Includes: Clean, lube and/or replace Brake Hardware as necessary. Adjust Brakes (where applicable). Includes: Repack Wheel Bearings (where applicable). DOES NOT include refinishing.]			Brock Schartz	1.00	105.00	105.00		105.00
-	Brake Rotor - Rear - Fleet	FT880869			2.00	173.14	346.28		173.14
-	Brake Pads - Rear - Ultra-Premium - Ceramic	UP8698X			1.00	83.00	83.00		83.00
Totals for Invoice:									
						846.83	210.00	0.00	
								1.66	
							1,056.83	7.88	
									1,066.37

Invoice: 007333, Posted On: 12/19/2024, SW: Moldovan, Ashley

Odometer in: 163,839 Odometer Out: 0

Time	Description	Part No.	Category	Technician	Qty	Sale	Extd	Price	Rate
0.30	Lube, oil, and filter 5W20 Lubricate and check chassis. Change oil and oil filter. Check air filter and breather filter. Check all fluid levels and tire pressures. Perform basic safety inspection. Road test vehicle.		Maintenance	Jack Neary	0.30	31.50	31.50		105.00
Notes - Fluid Capacity: Engine Oil - Volume: 7.00 QTS. (6.62L) - API - SAE 5W-20; 5.7L									
-	5W20 - ENGINE OIL	5W20			7.00	3.81	26.67		3.81
-	OIL FILTER	27060MP			1.00	4.01	4.01		4.01
Notes - NEEDS TIRES AND BRAKES									
0.50	HEADLAMP BULB - Remove & Replace - w/Halogen Lamps, One Side, Both, Low & High Beam - [DOES NOT include adjust.]			Brock Schartz	0.50	52.50	52.50		105.00
-	HEADLIGHT	9005N			1.00	17.34	17.34		17.34
Totals for Invoice:									
						48.02	84.00	0.00	
								0.66	
							132.02	0.73	
									133.41

Customer and Vehicle Report

Print Date: 09/15/2025

Vehicle: 2020 Dodge - Durango Pursuit, 5.7L V8 (345CI) VIN(T), B0312, 09

Average Daily Mileage: 132

Invoice: 007607, Posted On: 02/19/2025, SW: Moldovan, Marcel

Odometer in: 172,722 Odometer Out: 0

Time	Description	Part No.	Category	Technician	Qty	Sale	Extd	Price	Rate
	Lubricate and check chassis. Change oil and oil filter. Check air filter and breather filter. Check all fluid levels and tire pressures. Perform basic safety inspection. Road test vehicle.								
-	5W20 - ENGINE OIL	5W20	Maintenance		7.00	3.81	26.67	3.81	
-	OIL FILTER	27060MP	Maintenance		1.00	4.01	4.01	4.01	
Totals for Invoice:									
		30.68		0.00			62.18		
						0.25	0.73	0.00	63.16

Invoice: 007452, Posted On: 01/14/2025, SW: Moldovan, Ashley

Odometer in: 167,532 Odometer Out: 0

Time	Description	Part No.	Category	Technician	Qty	Sale	Extd	Price	Rate
0.30	Lube, oil, and filter 5W20		Maintenance	Jack Neary	0.30	31.50	31.50		105.00
	Lubricate and check chassis. Change oil and oil filter. Check air filter and breather filter. Check all fluid levels and tire pressures. Perform basic safety inspection. Road test vehicle.								
Notes - Fluid Capacity: Engine Oil - Volume: 7.00 QTS. (6.62L) - API - SAE 5W-20; 5.7L Eng - w/Filter									
-	5W20 - ENGINE OIL	5W20			7.00	3.81	26.67	3.81	
-	OIL FILTER	27060MP			1.00	4.01	4.01	4.01	
Totals for Invoice:									
		30.68		0.00			62.18		
						0.25	0.73	0.00	63.16

Invoice: 007338, Posted On: 12/20/2024, SW: Moldovan, Marcel

Odometer in: 163,874 Odometer Out: 0

Time	Description	Part No.	Category	Technician	Qty	Sale	Extd	Price	Rate
1.00	BRAKE SHOES &/OR PADS - Remove & Replace - Front Axle - [Includes: Clean, lube and/or replace Brake Hardware as necessary. Adjust Brakes (where applicable). Includes: Repack Wheel Bearings (where applicable). DOES NOT include refinishing.]			Brock Schartz	1.00	105.00	105.00		105.00
-	Brake Pads - Front - Fleet	FT8856A			1.00	126.09	126.09	126.09	
-	Brake Rotor - Front - Fleet	FT880870			2.00	145.73	291.46	145.73	

Celly's Auto Repair
 213 N Ogden; PO Box 427
 Lebo, KS. 66856
 Phone - 620-256-6411 Fax - 620-256-6036

Customer and Vehicle Report

COFFEY CO SHERIFF
 605 NEOSHO ST
 Burlington, KS, 66839

Print Date: 09/15/2025

Vehicle: 2020 Dodge - Durango Pursuit, 5.7L, V8 (345CI) VIN(T), B0312, 09

Invoice: 007776, Posted On: 03/25/2025, SW: Moldovan, Ashley

Time Description		Part No.	Category	Technician	Qty	Subtotal		Hazard Mat		Supplies		Tax		Total	
-	TIRE REPAIR - DRIVER REAR	TR REPAIR		Jack Neary	1.00	15.00		0.23		15.00		0.00		15.96	
Totals for Invoice:						15.00		0.00		0.73		0.00		15.96	

Average Daily Mileage: 132

Odometer in: 0 Odometer Out: 0

Invoice: 007750, Posted On: 03/17/2025, SW: Moldovan, Marcel

Time Description		Part No.	Category	Technician	Qty	Subtotal		Hazard Mat		Supplies		Tax		Total	
Notes - Fluid Capacity: Engine Oil - Volume: 7.00 QTS. (6.62L) - API - SAE 5W-20; 5.7L Eng - w/Filter															
0.30	Lube, oil, and filter 5W20		Maintenance	Marcel Moldovan	0.30	33.00		33.00		33.00		0.00		110.00	
Lubricate and check chassis. Change oil and oil filter. Check air filter and breather filter. Check all fluid levels and tire pressures. Perform basic safety inspection. Road test vehicle.															
-	OIL FILTER	27060MP	Maintenance		1.00	4.01		4.01		4.01		4.01			
-	WIPER BLADE	NP21	Maintenance		2.00	16.36		8.18		16.36		8.18			
-	5W20 - ENGINE OIL	5W20	Maintenance		7.00	26.67		3.81		26.67		3.81			
Totals for Invoice:						80.04		0.00		0.73		0.00		81.03	

Odometer in: 176,169 Odometer Out: 0

Invoice: 007607, Posted On: 02/19/2025, SW: Moldovan, Marcel

Time Description		Part No.	Category	Technician	Qty	Subtotal		Hazard Mat		Supplies		Tax		Total	
Notes - Fluid Capacity: Engine Oil - Volume: 7.00 QTS. (6.62L) - API - SAE 5W-20; 5.7L Eng - w/Filter															
0.30	Lube, oil, and filter 5W20		Maintenance	Brock Schartz	0.30	31.50		31.50		31.50		0.00		105.00	

Odometer in: 172,722 Odometer Out: 0